

Notice



CORRECTION
 SERVICE FLASH

PRODUCTION CHANGE
 ADD INFORMATION

FILE NO.

Please add this notice to the Service Manual listed below.

Category: COLOR TELEVISION

Date: FEBRUARY / 07 / 2012

Model: DP46841

Effective from : Chassis No. P46841-02

Destination: U.S.A. / CANADA

REF : No. SM780189-02

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. **If the Service Manual Chassis No. does not match the unit's**, additional Service Literature is required. This chassis is similar to Chassis No. P46841-00. Only the **difference** Service Information is given in this manual. For detailed Service Information, refer to the **Original Service Manual** and **Notices** for Chassis No. P46841-00 used in Model DP46841 (SM780189).

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

The are no changes.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The are no changes.

3. PWR ON LED POSITION CHANGE

Before (Z5WF): Right side

Current (Z5WFE): Left side

For parts or service contact:

Sanyo Manufacturing Corporation
P.O. Box 2000
3333 Sanyo Road
Forrest City, Arkansas 72335-2000